

CLASSIFIED MESSAGE

DATE 0115Z 11 JAN 61

~~TOP SECRET~~

ops

TO DIRECTOR

FROM [REDACTED]

ACTION DPD (1,2,3,4,5,6,7,8,9,10)

INFO S/C (11)

RR

TOR: 0610Z 11 JAN 61

25X1

PRIORITY

IN 42197
25X1

TO OPIM [REDACTED]

PRITY [REDACTED]

CON [REDACTED]

25X1

25X1

FORWARDS FOLLOWING CAMERA OPERATION REPORT RE MISSION 3023.

1. NO EVIDENCE OF CONDENSATION, VACUUM FAILURE, OR TEARS ON RECEIVE MATERIAL.

2. TWO FACTORY SPLICES WERE FOUND ON THE "R" ROLL.

3. DIFFICULTIES ENCOUNTERED DURING PROCESSING.

A. CREASES AND TEARS OF FILM OCCURRED ON THE "R" ROLL OF ONE OF THE MAGAZINES. THE PROCESSOR'S FILM LOCK LATCH WAS DEFECTIVE AND CAUSED A GREAT DRAGGING ACTION ON THE FILM AS IT METERED OUT. THE FILM WAS CUT TO PREVENT FURTHER DAMAGE TO THE PRODUCT.

B. THE OTHER CREASES WERE CAUSED BY THE ERRATIC ACTION OF THE LAPSE ROLLER CLUTCHES.

4. A FOREIGN SPLICE WAS FOUND ON THE "R" ROLL EXPOSURE NR 1038. THIS SPLICE WAS MADE OF CLEAR ACETATE TAPE APPROX 1 AND 1/3 INCH WIDE.

5. PROCESSING DATA.

25X1

~~TOP SECRET~~

RECEIVED BY [REDACTED]
DATE 18 JAN 61
TIME 18486

25X1

~~TOP~~ SECRET

PAGE 2

DEVELOPER D-19 REPLENISHER D-19 250 CC/MIN

PROCESSING SPEED 5 FT/MIN S8 F

GAMMA LOW 1.92 HIGH 2.10.

END OF MESSAGE

~~TOP~~ SECRET